

MATORK / 22 MEGABYTE

ENHANCEMENTS

(CORE VERSION)

Copyright Mator Systems 1982

MATOR SHARK WINCHESTER DOS ENHANCED FEATURES

The following notes provide a brief description of the extra facilities which the MATOR SHARK WINCHESTER DOS provides in addition to the emulation of the Commodore PET DOS Version 2.5.

1. As mentioned in the MATOR SHARK System Description, the Winchester disc drive contained within the SHARK is partitioned into two logical drives, each containing 299 tracks and each track containing 138 256-byte sectors. Track 0 of the disc is reserved for the MATOR Volume Header, Error Map and Reallocation Map, and tracks 599 and above are reserved for defective sector reallocation.

The disc is physically formatted at the factory but if required may be reformatted using the "KILL" command. This is a new command within the DOS. Its format is "KILL:i" where i is the Interleave Sequence Number. At the factory the disc has been formatted with i=7. This number provides the facility to space out, round a track, logically consecutive sectors, i-1 sectors apart.

This facility allows the user to optimise his physical disc layout to match his controller/host processor speed.

The "KILL" command takes approximately 25 minutes to execute. During a disc (re)format any defective sectors are reallocated in track 599 onwards.

The DOS "NEW" command simply (re)initialises one or other of the two logical discs into PET-compatible format i.e. it sets up the BAM and directory of the disc in question. Therefore the "NEW" command does not take long to execute - approximately 20 seconds. If a disc ID is not specified, a default ID of "spaces" is used.

2. The maximum capacity of an individual Relative File has been increased to over 1.7 Megabytes, compared with the 170 KB maximum imposed by the 8050 DOS. Otherwise, Relative File operation is as for the 8050.

3. The following error messages differ from those produced by the 8050 DOS. They are all related to the physical disc controller.

| ERRR NO. | MESSAGE | MEANING |
|----------|---------------------|--|
| 22 | READ ERROR | Illegal Disc Command (System error) |
| 23 | READ ERROR | Read Error after Retry Count exhausted |
| 25 | WRITE ERROR | Write Error after Retry Count exhausted |
| 26 | WRITE PROTECT ON | Protect error |
| 27 | DEFECT OVERFLOW | Out of space in Defective Sector Reallocation Area |

Errors 22 and 26 will not occur in ~~normal~~ running. A user cannot WRITE PROTECT the disc or issue an ILLEGAL ~~DEC~~ COMMAND.

All other error messages have the same meaning as in the 8050 DOS.

4. Two new commands have been implemented to help the SHARK user recover from disc error situations.

In the unlikely event of an irrecoverable read/write error (reported by error codes 23 or 25), the user has available the following facilities -

1) BLOCK-CORRECT (B-C)

The syntax for this command is similar to that of the "BLOCK READ" command. It is "B-C:"ch,dr,t,s. The effect of this command is to reformat the selected sector, preserving the data held within the sector if at all possible, and will probably clear a read/write error. If the error is not cleared then the "BLOCK DEFECTIVE" command should be used (see below).

11) BLOCK DEFECTIVE (B-D)

The syntax for this command is again similar to that of the "BLOCK READ" command. It is "B-D:"ch,dr,t,s. The effect of this command is to reallocate the selected sector, preserving the data held within the sector if at all possible, into the effective sector reallocation area. Subsequently, any reference to this sector will automatically be redirected to its new physical location on the disc.

For both these commands, a channel ~~must~~ must be specified, but it is of no particular significance.

If it is practical to do so, the data in the reformatted/reallocated sector should be checked for correctness, since there can be no guarantee that it has been read from the faulty sector correctly.

5. By switching Switch number 8 of the controller's internal switch bank ON, memory access commands (M-R, M-W) using an address in the range 0100 Hex to 1FFF Hex (the 8050 disc buffer areas) will automatically be redirected to the equivalent SHARK disc buffer locations. By switching this switch OFF, no redirection will take place. In either case, addresses outside the above range are unaffected.

6. Please note that the microprocessor used within the SHARK controller is an Intel 8085A, rather than a MOS 6502 as in the Commodore 8050. An Intel 8085A will not execute 6502 assembler code!